



INVITATION TO BID #2017-80
Boyer Drive Extension Project ("BID")
RESPONSE TO CLARIFYING QUESTIONS #1
October 9, 2017

Note that these are questions submitted by interested firms to the above referenced solicitation. The below answers are for clarification purposes only and in no way alter or amend the BID as published.

1. *I can't find sign 16 in the sign plan layout sheets.*

Answer: See Sheet SS-2, SE corner of Fuller/King, mounted along with signs 3B, 12 and 18. The note also indicates to remove/save/reinstall the existing sign 12 (stop).

2. *Sign 2 says to mount on wood post in the data table but doesn't say anything in the sign plan layout sheets.*

Answer: See Sheet SS-1. Sign 2 is the existing private signage for the apartment building, located on the SW corner of Fuller/Monroe (all signs with broken borders are existing per note on SS-9). Plan directs to remove/save/reinstall sign behind the new right-of-way line on the same corner. The intent is to reuse the existing wood support.

3. *Is there a bid item for wood posts?*

Answer: There are no new wood supports on the project, hence no bid item. Wood support for Sign 2 is being re-used as noted above.

4. *Sign 4 in the data table doesn't show up on the sign layout sheets and say to mount above sign 12.*

Answer: See Sheet SS-1. Sign 4 is an existing Baskin Robbins sign that is to be removed. Sign 3B (Fuller) is the one that gets mounted above sign 12 (stop sign).

5. *There is no sign 12 at station Full 23+00 in the data table.*

Answer: Sign 12 (existing sign to be saved and reinstalled) is to be located at Station "FULL" 28+83, as shown in the table. See Question and Answer No. 1 above.

End of Clarifying Questions #1