



GEORGE MARLTON, JD  
PROCUREMENT DIVISION DIRECTOR

PROCUREMENT DIVISION  
PUBLIC SERVICES BUILDING  
2051 KAEN ROAD | OREGON CITY, OR 97045

REQUEST FOR QUOTES #2018-58  
**DIESEL TANK MOLD REMOVAL**  
RESPONSE TO CLARIFYING QUESTIONS  
August 9, 2018

Note that these are questions submitted by interested firms to the above referenced solicitation. The below answers are for clarification purposes only and in no way alter or amend the RFQ as published.

1. *The Riverstreet Pump Station was mentioned in the scope of work as reporting problems. What issues were reported?*

**Answer:** The filters were plugged in which mold was found.

2. *Are there photos of the tanks? These photos would allow us to determine if there are access issues our techs would be dealing with in order to access the tank for cleaning.*

**Answer:** There are currently no photo's available, but a complete site-visit will be conducted with the resulting Contractor. The diesel tanks sit next to or under the generators at each site. Each generator has a double door for access that is very close to the driveway and should have plenty of room to move around.

3. *The scope of work mentions "This project will entail sampling of the fuel and developing a treatment plan to take care of each site." We would approach this by having our tech travel to the site, pull a sample with a bacon bomb, conduct a field analysis then execute on a plan of action while on site. Does this sync with your vision of how the scope of work would progress?*

**Answer:** Pulling samples pre-test and post-test are acceptable means for servicing each site.

---

End of Clarifying Questions